






BLUEPRINT EXAMPLES



IBUILDTHE419.COM



Plan Symbols






Figure XI.2 Typical Control Wiring Diagram

Groove							
Square	Scarf	V	Bevel	U	J	Flare-V	Flare-bevel
Fillet	Plug or slot	Stud	Spot or projection	Seam	Back or backing	Surfacing	Edge
Weld all around	Field weld	Melt through	Consumable insert (square)	Backing or spacer (rectangle)	Contour		
					Flush or flat	Convex	Concave

Figure XII.2 Basic Weld Symbols



IBUILDTHE419.COM